



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000847A

DATE: 27-Jan-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	DS1836A-10+	N/A			Part reactivated from prior notice: M000847
Reactivation	DS1836A-5+	N/A			Part reactivated from prior notice: M000847
Reactivation	DS1836AS-10+	N/A			Part reactivated from prior notice: M000847
Reactivation	DS1836AS-5+	N/A			Part reactivated from prior notice: M000847
Reactivation	DS1836B-10+	N/A			Part reactivated from prior notice: M000847
Reactivation	DS1836BS-5+	N/A			Part reactivated from prior notice: M000847
Reactivation	DS1836C-10+	N/A			Part reactivated from prior notice: M000847
Reactivation	DS1836CS-10+	N/A			Part reactivated from prior notice: M000847
Reactivation	DS1836CS-10+T&R	N/A			Part reactivated from prior notice: M000914I
Reactivation	DS1836DS-20+	N/A			Part reactivated from prior notice: M000847

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 27-Feb-2017