

Micron Technology, Inc. 8000 S. Federal Way PO Box 6 Boise, ID United States

EOL of Select DRAM and Modules

PCN: 32555

Published: 2017-12-21

Туре:	End of Life			
Description:	to bette product	In an effort to maximize the manufacturing efficiency for Micron's DRAM product line and to better align with industry trends, Micron will End of Life (EOL) the below list of products. Micron is taking these actions to better focus efforts on supporting products that deliver the most value to our customers		
Reason:	Better /	Better Align With Industry Standard, Manufacturing Efficiency		
Product Affected:	Select	Select MPNs from multiple DRAM designs and process nodes		
Affected Micron Part Number		Recommended Replacement	Customer Part Number	
Component				
MT40A4G4NRE-083E C:B		CONTACT SALES REP		
MT44K64M18RB-083E:A		MT44K64M18RB-083F:A		
MT44K64M18RB-093F:A		MT44K64M18RB-083F:A		
MT53B256M64D2NW-062 WT:C		CONTACT SALES REP		
MTA18ADF2G72PZ-2G6H1R		MTA18ADF2G72PZ-2G6D1		
<u>Module</u> MT4KTF12864HZ-1G6K1		CONTACT SALES REP		

*Materials that have been ordered are in **bold**.

Method of Identification:	Marketing Part Number		
Micron Sites Affected:	All Sites		
Last Purchase Date*:	2018-06-21		
Last Shipment Date:	2018-12-21		

*Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.